

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2010 Levee Inspection Results**

**Lake County Watershed Protection District**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Lake County Watershed Protection District**

Waterway			Bank	Unit Miles
Unit No. 01 Middle Creek			Left	3.42

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/18/2010 - 5/18/2010			
DWR Inspector	Bob Duffey			
Accompanied By	Tom Smythe Lake Co.			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Middle Creek						Left	3.42	05/18/2010 05/18/2010	Bob Duffey

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	2.10	2.10	Earthen Levee	Trim / Thin Trees	LS	C	Trim trees to at least five feet above ground level.	39.162298 ° -122.915543 °	39.162298 ° -122.915543 °	12

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Lake County Watershed Protection District**

Waterway				Bank	Unit Miles
Unit No. 02 Middle Creek				Right	3.13
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/18/2010 - 5/18/2010				
DWR Inspector	Bob Duffey				
Accompanied By	Tom Smythe Lake Co.				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Middle Creek						Right	3.13	05/18/2010 05/18/2010	Bob Duffey

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.20	0.20	Earthen Levee	Encroachments	LS	CO	Buildings	39.187039 ° -122.908880 °	39.187039 ° -122.908880 °	1 Y
2	1.03	1.04	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	39.177218 ° -122.913673 °	39.176992 ° -122.913642 °	7
3	1.05	1.05	Earthen Levee	Encroachments	LS	PO	Buildings	39.176875 ° -122.913685 °	39.176875 ° -122.913685 °	5

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Middle Creek	Right	3.13	05/18/2010 05/18/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.20
End Levee Mile	0.20
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of the vegetation and building next to the landside toe of levee.

rduffey\_s\_20100616\_044.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Lake County Watershed Protection District**

Waterway			Bank	Unit Miles
Unit No. 03 Scotts Creek			Left	1.35
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/18/2010 - 5/18/2010			
DWR Inspector	Bob Duffey			
Accompanied By	Tom Smythe Lake Co.			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 03 Scotts Creek				Left	1.35	05/18/2010 05/18/2010	Bob Duffey	

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.91	0.99	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	39.159733 ° -122.921081 °	39.160088 ° -122.922590 °	1 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Scotts Creek	Left	1.35	05/18/2010 05/18/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.91
End Levee Mile	0.99
Location	Water Side
Category	Earthen Levee
Item	Vegetation

View of the vegetation along the water side slope of the levee.

rduffey\_s\_20100616\_045.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Lake County Watershed Protection District**

Waterway			Bank	Unit Miles
Unit No. 04 Page, Alley and Clover Creek Diversion			Right	1.53
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/18/2010 - 5/18/2010			
DWR Inspector	Bob Duffey			
Accompanied By	Tom Smythe Lake Co.			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Page, Alley and Clover Creek Diversion							Right	1.53	05/18/2010 05/18/2010	Bob Duffey

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.90	0.90	Earthen Levee	Encroachments	LS	M	Garbage	39.178545 ° -122.896648 °	39.178545 ° -122.896648 °	1 Y
2	1.05	1.18	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	39.180479 ° -122.896567 °	39.181947 ° -122.895112 °	2
3	1.41	1.41	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	39.184842 ° -122.893368 °	39.184842 ° -122.893368 °	3

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Page, Alley and Clover Creek Diversion	Right	1.53	05/18/2010 05/18/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.90
End Levee Mile	0.90
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of the garbage and wood on the landside slope of the levee.

rduffey\_s\_20100625\_079.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Lake County Watershed Protection District**

Waterway				Bank	Unit Miles
Unit No. 05 Clover Creek and Clover Creek Diversion				Left	1.04
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/18/2010 - 5/18/2010				
DWR Inspector	Bob Duffey				
Accompanied By	Tom Smythe Lake Co.				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Clover Creek and Clover Creek Diversion						Left	1.04	05/18/2010 05/18/2010	Bob Duffey

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.30	0.30	Earthen Levee	Vegetation	LS	M	Elderberries are blocking visibility and flood fight capability.	39.176957 ° -122.898673 °	39.176957 ° -122.898673 °	3 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Lake County Watershed Protection District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Clover Creek and Clover Creek Diversion	Left	1.04	05/18/2010 05/18/2010	Bob Duffey

Levee Mile Report Line	1
Start Levee Mile	0.30
End Levee Mile	0.30
Location	Land Side
Category	Earthen Levee
Item	Vegetation

View of the elderberries along the landside toe of the levee.

rduffey\_s\_20100625\_080.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected